



RECALL CAMPAIGN BULLETIN

Reference:

NTB08-003

Date:

January 19, 2008

**VOLUNTARY EMISSIONS RECALL CAMPAIGN
2008 PATHFINDER V-8 EMISSION LABEL****CAMPAIGN I.D. #** R0714**APPLIED VEHICLE:** 2008 Pathfinder (R51) with V-8 engine**APPLIED VINs:** 5N1BR18**8C 600000 - 644269**INTRODUCTION**

Nissan has determined that some 2008 Pathfinders with V-8 engines were manufactured with an incorrect underhood Vehicle Emission Control Information (VECI) label. The label contains an incorrect letter in the emission test group code. The VECI label contains the code that tells a testing facility which test to perform to ensure the vehicle is tested to the correct standard. The U.S. Environmental Protection Agency and California Air Resources Board consider the underhood VECI label an integral part of state emission testing. If the label is incorrect, the vehicle may subsequently fail that test even if it meets applicable emissions standards.

To remedy this, Nissan is conducting a voluntary emission recall campaign. A replacement label is being mailed to affected customers along with instructions on how to affix. Nissan is also offering customers an option of bringing their label to a dealer and have the dealer install it free of charge for parts or labor.

IDENTIFICATION NUMBER

Nissan has assigned identification number R0714 to this campaign. This number must appear on all communications and documentation of any nature dealing with this campaign.

NUMBER OF VEHICLES POTENTIALLY AFFECTED

The number of vehicles potentially affected by this campaign is approximately 4,775

DEALER RESPONSIBILITY

It is the dealer's responsibility to check Service Comm for the campaign status on each vehicle falling within the range of this voluntary recall which for any reason enters the service department. This includes vehicles purchased from private parties or presented by transient (tourist) owners and vehicles in a dealer's inventory. Nissan strongly encourages dealers to correct any new or used vehicles in their inventory before they are retailed.

SERVICE PROCEDURE

NOTE: DO NOT REMOVE THE EXISTING VEHICLE EMISSION CONTROL INFORMATION (VECI) LABEL. Install the replacement label over the top of the existing label.

1. Park the vehicle in a safe place.
2. Set the transmission in “P” position and apply the parking brake.
3. Turn the ignition “OFF”.
4. Open the engine hood and use the hood support rod to hold the hood open.

WARNING: The engine compartment components may be extremely hot! Always allow sufficient time for cooling before performing any work under the hood.

5. Locate the existing under-hood VECI label.
6. Clean the label and the area around it with a mild detergent and water.

NOTE:

- Care should be taken not to use harsh chemicals that may damage the existing label.
- It is important the surface be free of dirt and oil to ensure proper adhesion of the new label.




Figure 1

7. Completely dry the label and the area around it.
8. Peel the new label from the backing sheet and install it directly over the top of the existing label.

NOTE: The adhesive on the label is permanent. Extra care should be taken when applying the new label since it can not be moved once it is attached.




Figure 2

PARTS INFORMATION

DESCRIPTION	PART #	QUANTITY
Emission Label	14805 - ZS02B	1

CLAIMS INFORMATION

Submit a Campaign (CM) line claim using the following claims coding:

“CM” I.D.: R0714

DESCRIPTION	OP CODE	FRT
Install New Emission Label Over Existing Label	R07140	0.2

OWNER'S LETTER

Dear Nissan owner:

Nissan is committed to providing the highest levels of product quality and customer satisfaction. Nissan has decided that your 2008 Pathfinder V-8 was manufactured with an incorrect underhood Vehicle Emission Control Information (VECI) label. The label contains an incorrect letter in the emission test group code.

Reason for Recall

The VECI label contains the code that tells a testing facility which test to perform to ensure the vehicle is tested to the correct standard. The U.S. Environmental Protection Agency and California Air Resources Board consider the underhood VECI label an integral part of state emission testing. If the label is incorrect, your vehicle may subsequently fail that test even if it meets applicable emissions standards.

What Nissan Will Do

Provided with this notification is a replacement VECI label with the correct emission test group. Also included (on the reverse side of this letter) are instructions for the installation of your replacement VECI label.

What You Should Do

Please replace the VECI label on your vehicle with the one included with this notice. Installation instructions are provided on the reverse side of this letter. The actual time to replace the label is approximately 10 minutes. If you prefer, contact your Nissan dealer and make an appointment to have the new label installed at **no charge** to you. Please bring this notice and replacement label with you to the service appointment. If the dealer fails, or is unable to make the necessary repairs free of charge, you may contact the National Consumer Affairs Department, Nissan North America, Inc., P.O. Box 685003, Franklin, TN 37068-5003. The toll free number is 1-800-NISSAN1 (1-800-647-7261).

Thank you for your cooperation. We are indeed sorry for any inconvenience this may cause you.